

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-024804**Date Inspected:** 26-Jun-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Mr. Li Yang ZPMC**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Bay 14 Lift14W and Bay 16 Bike Path**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector Robert A. DeArmond was present during the time noted above and conducted observations relative to the work being performed.

BAY 16**Ultrasonic Testing (UT)**

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. All components were as listed on NWIT notification no. 09594. The member(s) is/are identified as OBG Bike Path Path. The weld designations reviewed are as follows

BKSA008-001-001~004, BKSA010-001-001~004, BKSA010-001-001~004

BAY 14**Magnetic Particle Testing (MT) / ABF Tracking**

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ABF Quality Control / Quality Assurance personnel. This QA Inspector generated an MT report for this date. All components were as listed on NWIT notification no. 09605. The member(s) is/are identified as Lift 14W Rib Stiffener to Floor Beam, Floor Beam Flange Splice, Rib Stiffener to Bottom Plate, and Floor Beam Flange to Longitudinal Diaphragm. The weld designations reviewed are as follows:

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SEG3020J-100, SEG3020J-056, SEG3020N-075, SEG3020N-076, SEG3020N-077, SEG3020X-016,
SEG3020X-069, SEG3020X-049, SEG3020X-043, SEG3020X-039

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

As mentioned above between QA and QC concerning this project

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Jim Devy 150-002-6784, who represents the Office of Structural Materials for your project.

Inspected By:	DeArmond,Robert	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer
